

COMPRESS UV600s INK CHARGE OR LITTLE CHARGE PROCEDURE



- 1- Power down the machine, press load/eject button and hold them down
- 2- Press forward/reverse/next button and hold them down also
- 3- Switch on machine and keep holding down the above-mentioned buttons
- 4- After a short time the blue power light on control panel will flash and the screen will display CHECK TEST, you can now let go of load/eject/for/rev/next
- 5- Screen will show RAM CAPACITY, press cancel
- 6- Screen will show CHECK TEST
- 7- Push the media tray all the way to the back of the machine and pull forward approx. 2cm. wait for the load LED to go RED
- 8- Press the load button and load LED will go green
- 9- Screen will display RAM CAPACITY, press cancel
- 10- Screen will display CHECK TEST
- 11- Press NEXT 2 times until screen displays CLEANING
- 12- Press ENTER and machine will do a short 5 second clean
- 13- Screen will display NORMAL
- 14- Press the NEXT button several times until you see either LITTLE CHARGE or keep pressing NEXT until you see INK CHARGE